



Recommended Steps to Install the driver


Do these steps without connecting the device to PC

Extract the zip file CDM 2.08.30 WHQL Certified .zip as shown in the figures







Run the CDM v2.08.30 WHQL Certified.exe from the extracted zip file.




Press Extract button



Press Next button



Press Next button. It should install the drivers and following screen should appear.



Now connect the hardware. Check the device manager as given in the figure. It should show a COM port.

In this case COM port 16 is the new COM port and it is used by the CANMate application.

